



AMPS Premises Security Assessment

PREMISES NAME	Stroud Library
ADDRESS	Lansdown,Stroud,Glos,GL5 1BB
TF CODE	081101
DATE OF SURVEY	21/12/2022.
DELIVERY OFFICER	Richard Hitchins .

Security Incidents

1) Incidents of crime in the local area (In the last 12 months)

Comments: Likely event minor consequence/Limited measures in place

No incidents of crime in the local area.

2) Attacks/threats to staff or service users

Comments: Very unlikely event or low consequence/Measures in place

No verbal attacks or threats on staff.

3) Intruders inside buildings incidents

Comments: Low Risk/Effective Measures

No incidents.

4) Trespass

Comments: Low Risk/Effective Measures

Yes, On to roof.

5) Vandalism Incidents

Comments: Low Risk/Effective Measures

Yes, incidents of vandalism.

6) Theft/Burglary incidents

Comments: Low Risk/Effective Measures

No incidents of Theft/Burglary.

7) Fire Incidents

Comments: Low Risk/Effective Measures

No incidents of Fire.

8) Alcohol and Drug incidents

Comments: Very unlikely event or low consequence /Measures in place

No evidence of Alcohol or drug incidents.

Buildings & Grounds

1) Access to the public

Comments: Low Risk/Effective Measures

Yes.

2) Site overlooked from roads/or other buildings and houses

Comments: Very unlikely event or low consequence /Measures in place

Yes site is overlooked by residential & Commercial properties.

3) Boundary Fences and Gates

Comments: Very unlikely event or low consequence /Measures in place

Yes site is open front with security fence to sides and rear of property.

4) Entrance

Comments: Low Risk/Effective Measures

Yes entrance is clearly defined.

5) Reception

Comments: Low Risk/Effective Measures

Yes library receptions is clearly located 1st floor

6) Visitor Control

Comments: Low Risk/Effective Measures

No visitor control system in place, doors on ground floor and 1st floor can be locked.

7) Staff entrance

Comments: Low Risk/Effective Measures

Yes there are a number of alternative entrance to access and exit.

8) Meeting rooms

Comments: Low Risk/Effective Measures

Yes used as a Drop in Hub.

9) Secure exit doors

Comments: Very unlikely event or low consequence /Measures in place

Yes exit doors are secure.

10) Windows

Comments: Very unlikely event or low consequence /Measures in place

Yes windows are secure.

11) Condition of building

Comments: Low Risk/Effective Measures

Building is in a good order.

12) Detached and Temporary Buildings

Comments: Low Risk/Effective Measures

None.

13) Car Parks

Comments: Very unlikely event or low consequence /Measures in place

Yes car parking is under library (Staff only)

14) Hiding places

Comments: Unlikely event or low consequence /Measures in place

Yes-If access can be gained rear of property.

15) Waste bins

Comments: Low Risk/Effective Measures

Yes bins are located in Garage area.

16) Valuable equipment

Comments: Very unlikely event or low consequence /Measures in place

Yes fixed computers.

17) Out of hours' use

Comments: Low Risk/Effective Measures

Yes –Drop in Centre.

18) Lone working

Comments: Low Risk/Effective Measures

Yes occasional.

Security Measures

1) Reporting

Comments: Low Risk/Effective Measures

No issues.

2) Staff Behaviour

Comments: Low Risk/Effective Measures

Have procedures in place to deal with issues /conflict with Public.

3) Fire Precautions

Comments: Low Risk/Effective Measures

Yes-Fire Alarm installed with smoke detection.

4) Security Lighting

Comments: Low Risk/Effective Measures

Yes external lighting.

5) CCTV

Comments: High Risk/Absence of Measures/Effective Measures

Yes.

6) Intruder Alarm

Comments: Low Risk/Effective Measures

Yes.

7) Surveillance /Security patrols

Comments: Low Risk/Effective Measures

No GCC do employ a security company who will respond to any incidents.

8) Cash Handling

Comments: Low Risk/Effective Measures

Yes.

9) Property Marking

Comments: Very unlikely event or low consequence /Measures in place

None.

Recommendations

Yes –Based on the information provided at the time of the inspection the following recommendation is made.

- a) Access can be gained to rear of property via neighbouring Property, Youth drop down on to Fire exit escape route pathway which allows access onto Main Library roof area. Consider addition Security fencing bounding neighbours property. On Hold Future of property under review.